DFD-4622-61

20 July 1961

MENADIN WE I Acting Chief, DRO-DO/

SUBJECT S S-AST/Si-4 Helicopter Comparison

L. There is not sufficient quantitative data available to make an accurate comparison between the Hi-A and the Manna H-ATD. Recently, tests were conducted at the AFFIG. Mineris Air Force Fase, California, on the Hi-A. Proliminary results of the harding qualifies are evalled as but no performance data have been substited. The only significant figures presented are: capty wright - 11,711 penals, and overload wright - 15,765 panals, and overload wright - 16,647 panals. These psyloads of 4,456, and 5,236 pounds are not given with any set of test conditions or operational limitations. They are also at variance with the data of the "Characteristics and Forfermance Handbook U.S.S.E. Aircraft." The data given in this official decreent is dated September 1957.

As the bendling data presented on the H-ASS in AFFE-IN-CO-21, Cated Cotober 1960, has caused such controversy. The conflicting statements within the body of the report and the lack of inclusion of particent suddictations and and tested prior to the report subsistent tend to deposit confidence in the evaluation. The report states that a sajer operational discrepancy is, mong others, "pear flying qualities." Later in this same report, under the order training section, the following statement is made: The H-ASD is a rolatively easy sixplane to fly. Filots can be solved in the sixraft after approximately 4 hours of transition." As with the AFFE preliminary report of the H-A, no performance figures are quoted.

5. Only a limited execut of performance data is available from the Standard Alsonalt Characteristics handbook. The data are not consistent in that payload capabilities vs. altitude cannot be compared with range data. The range data is presented for optimum altitudes of 5,000 and 1,000 feet. The advance altitude of 14,000 feet has no such data. The data on the H-431 is dated 12 January 1959 and on the H-4 is dated September 1957. These data are, no doubt, obsolete but are the best source available at this time. The comparative data are:

2 7 2011

Approved For Release 2000/05/16 : CIA-RDP81B00880R000100110002-9

		DFD-4622-61 Pago 2
	ar-H	EA-4
Pario wight Cover with 10% courses Cover with 10% courses Cover with 10% courses Cover with 10% courses Cover with 10% courses	4,355 1,020 5,775 6,900 1,255 21,900 EL	10,000 1,700 <u>A00</u> 12,500 13,600 2,500 120
Hovering couling with 2004 paylow England load	16,500 4,419	17,500 11,700

- As From conversation with the AFTC pilot who has flow both evaluations, give the edge to the H-455 to perform the classics. This is the to the hamiliary characteristics comparison. He stated that the to the design of the engine/rotor combination of the M-4, the pilot is ferred to react to changes in flight conditions rather than have the ability to change the conditions at will. He said the Hi-4 met, in general, he operated as a fixed wing aircraft and take-offs and landings should be accomplished using a relatively large classed area. Even at sea level conditions, take-offs and landings out of haver conditions present hazardous operational characteristics in the H-4. The Meards AFO pilot did not believe the H-4 could eafely perform may receiply missions at 14,000 feet or above.
- 5. Farferments data received by telephone from the Inglesering Branch of Edwards AFB is as follow:
 - (A) The H-430 at a take-off weight of 7,100f can carry 1900f of useful loss 100 neutical miles, off lead the cargo and return without refueling. Average cruise speed would be 98 kmets. It would have a fuel losing of 1200 pounds and a crew of two. Trains in lost vs. crew could be made. The H-430 could not hover out of ground effect at take-off weight and would require 450 feet of cleared area to reach 50 feet of altitude.
 - (D) Under the conditions of a 10°C hot day, the off lead capability he reduced to 500 pounds and the cleared area regularized is increased to 620 feet.
 - (6) By using non-recommended rolling take-off techniques requiring a ground roll of 580 feet, the useful load could be increased to 1900 pounds on a standard day. The range would decrease to 97 miles and the belicopter could only hover at 5 feet above the ground at the off load point.

DF0-4622-61 Page 3

- (D) If the temperature were 10°C hotter for condition C above, the payload would decrease to 850 pounds and the take-off roll increase to 750 feet.
- (B) Due to the extreme nose down pitch with engine loss and unsatisfactory handling characteristics of the M-43B above M,000 feet altitude, Edwards AFB does not recommend that such missions be attempted.
- (F) Performance of the Mi-4 at 14,000 feet elevation is extremely limited. With zero usefulload, the helicopter cen haver at 15 feet above the terrain. With 1,000 pounds of cargo, this haver altitude is reduced to 5 feet. With 2,000 pounds of useful load, the Mi-4 has no hover capability at 14,000 feet. An estimated take-off ground roll for this condition is 2,000 feet. The above figures include a cross of two and a radius of action of 60 neutical miles.
- (6) Over-all, the performance of the H-43D is better than that of the M-4.
- 6. Conclusion: Due to the comments from Rivards AFB concurning the vehicle hardling characteristics, it is concluded that the H-AED would not present a favorable impression in attempting to perform the resupply mission in the altitude range of 14,000 to 18,000 feet.
- 7. Recementation: That the H-439 not be considered for performing resupply rissions at altitudes of 12,000 feet or above.

25X1A

L-DE/DID

1-UL/DED

DED/DEJORES

CONFIDENTIAL-SENSITIVE-MOFORM

FLIGHT REPORT

GENERAL COMMENTS

I COCKPIT EVALUATION:

East of Entry. Pilet entry was satisfactory. The leather hand grip facilitates entry without an objectional restriction. Co-pilet/Observer entry was not satisfactory, entry being made only from below through the cabin.

Seat Comfort. Satisfactory with and without chute. Seat adjustment unsatisfactory. Rudder pedal adjustment is satisfactory. Rudder trim tabs adjustment poor. An unnecessary feature in the aircraft is the extra weight carried because of the heavy construction of rudders. controls and numerous other items.

power subtrely Satisfactory; exclic stick, rudder pedals, collective and power subtrely Satisfactory; exclic stick, rudder and sollective controls were all comfortable. Cyclic grip was twisted at too large an angle clockwise by approximately 50°. No great concern. Throttle motion, the reverse of our standards, was not objectionable; however, the collective opring lock was very objectionable in other than statisfied flight.

force gradient expensives Endder forces too light. Trim indicators and gentroles Cyclic trim - North the seteral and longitudinal trim rate very good. Breakout force with indicate deptical approach addisent factory, Rudder trim device a Little askward to use and rate of trim too might sentent forces too light with

DOWNGRADED AT 12 YEAR
INTERVALS; NOT AUTOMATICALLY
DECLASSIFIED DOD DIR 5200.10

CONFIDENTIAL-SENSITIVE-NOFORM

Approved For Release 2000/05/16 : CIA-RDP81B00880R000100110002-9

a large "dead some" about trim. Trim indicators excellent.

Suitability of Seat Belt and Shoulder Harness. Awkward to use and adjust. 1938 vintage. Long ends of seat belt tend to fall into collective control.

Window and Door Operation. Easily operated. Nothing unusual. Heavy construction and required only one hand.

East of Operating Brakes. Hand operated brakes did not hinder operation.

Cabin and Mindshield Defrections. Provided, but not evaluated.

East of reading instructions for actuation of emergency controls.

anxibiary systems, circuit breakers, etc. Below our standards. The fire extinguisher system being provided for a single engine recip.

is good. Too many pilot motions required to operate it if proper directly breaker is not set. With tight shoulder etraps, fire button could not be reached. Auxiliary Serve switches unsatisfactory as placement required crowmen to turn off primary serve. Cowl flaps, etc. on pilot's left side excellent. Cowl flap switches on center console were not necessary. Circuit breakers satisfactory. Entery generator, etc. should be more closely situated to the pilot.

Consider the light up warning panels are too small in size.

Emergency Escape Provision. Pilot - satisfactors. Co-pilot - thus is factory in that he must jump down from the coskpin or so through the sabis. Grew and passengers hinted to escape through the small windows in the cabis or the one case door.

CONFIDERTIAL-SENSITIVE-NOTORN

COMPIDENTIAL-SENSIFIVE-NOFORM

Instrument Panels and Consoles. Satisfactory. Engine pressure and temperature instruments on the side of the Observer eliminates the large size instrument panel we are now forced to go to because of duplication. Ease of opening panel for repair by removing one aut is excellent. Location of starting switches and others needed during start are excellent. Panel and console are not outstanding, but addiquete for mission.

Electroniss System. Holmet and microphone are WW II type equipment; limited channel VHF. Intercom - uncatisfactory. Radio altimeter - excellent response. ADF met intelled

PLIGHT PEASE

STARTING CHARACTERISTICS:

With the exception of long list, of circuit breakers the starting system is relatively simple. The need to move the blades to the forward stop delays starting and the windmilling of the roter plus pre-ciling the transmission are two undesirable features. Shipboard operations must be restrictive! The external power source and the ability to start the sixcraft by hand crank in the syent of electrical trouble are desirable features for field use considering the missions warm up time of 10 minutes at approximately 80°7 is accessive. The latk of an cil hopper is a poor feature. Oil dilution and cold engine starts will displicate starting and restrict aircraft operationally. (iii temperature gage behind pilot is poor. Refer engagement is similar to the systems used in Te. St. jav. friction clutches. The four-position

Confidential-sensitive-hotorn

CONFIDENTIAL-SENSITIVE-NOFORM

colector and puch button are satisfactory, requiring approximately animites to ansage. Alreads recks overestively on engagement and theoretic rectains are poor during stop Al & 2 of engagement.

Sining each stop is also poor, indicating heat or friction clutch problems. The jumphone Al an antichaetery and the clutch oil procedure mass in a good indication to the pilot of positive jumphone and in a good indication to the pilot of positive jumphone the engine is not and the aircraft rocks. During stop for it the clutch engagement, the pilot could very enally forget to push the hutton to release friction. There is not any indication of initial reference to release button.

With warn ongine, stort and ongogoment can be made within 5 minutes.

Without warning at 75 - 80°F total time to 1800 RPM for start and

engagement averages 13 to 15 minutes. Strap-in time is 3 to 5 minutes.

minch ment bolts are poorly designed.

PAXT CHAVACTERISTICS:

indication of forward trim from object trim is required at 2200 EPM.

5° collective picche and 22 = 23 in MAPs. The aircraft turns wolk about one wheel and tamis backward without difficulty. The hand brake worked well) besever, taming about this would be restricted without differential brakes. Brake response excellent with proper smallfully. Only redders and collective are required for taxing turns. Order recommend above 2200 BPM was not apparent. Notes

Confidential-sensitive-noform

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9 CONFIDENTIAL-SENSITIVE-NOFORN

level in the cockpit during taxi with doors open was high. With pilot doors closed, it was satisfactory.

TAKEOFF AND HOVER:

Pre-takeoff check-eff list was small. Trim tabs had to be changed from starting position of $R=0^{\circ}$, $A=0^{\circ}$, and $E=1^{\circ}$ aft to $R=1^{\circ}R$, $A=1^{\circ}R$, and Longitudinal - 1° Fwd. (Book figures). However, I found it necessary to use R=2 to 2%° R, A=3/4° R, $E=0^{\circ}$.

It is interesting to note that the sircraft cockpit is not equipped with any check-off lists. When applying collective with full throttle approximately 7 to 10 seconds was required to apply collective in order to obtain maximum RPM in a hever of 2500 RPM. Trim change forces are very high unless trim is used. The trim device handles it well and elevator trim indicator presents the pilot with a good indication of eg and rudder trim of the rudder remaining.

Bover stability appears good since minimum cyclic motion is required to hold a spot. High stick forces increase pilot effort over that really necessary. Directional control power is very weak and is felt to be restrictive. Full directional control was applied many times. Outside observers report a large tail boon flexing when rudder is applied. Turns on the spot were restricted below desired for the size and mission because of the lack of rudder.

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9
CONFIDENTIAL-SENSITIVE-NOFORN

Take-off at 15,800 lbs and density altitude flows required IGE techmique time to accelerate to climb speed was excessive with main concentration on rotor/engine RPM to provent day drop or less of RPM.

and tiring motion and grip to the pilot's hand on the collective.

The plunger lock on the collective hindered operation during hover and take-off. Field of view over the ness and to the right of the pilot was very restrictive. With the cockpit doors closed, field of view was below exfety standards and would hinder formation flight. In any banked turns over 10°, the pilot could not see the horizon in the direction of the turn.

IN-FLIGHT CHARACTERISTICS

Power adjustment from an operational viewpoint was satisfactory in level flight. Trimmability was acceptable, however, not approaching that of a fixed wing aircraft. The pitch change with speed in level flight is very small and will aid in instrument flight, Control harmony is poor. Weak rudder forces, high cyclic forces and lateral trim change with speed are below U. S. aircraft. The stable retersystem and apparent short period damping make the aircraft less fatiguing to fly in turbulent air. Conversation with H-34 indicated he was having a rough ride whereas the test aircraft required only longitudinal inputs of a smaller amount (inputs per time period) to dampen long period oscillations. Since roll is adversely coupled with pitch, more inputs lateral were required. Directional axis

CONFIDENTIAL-SENSITIVE-NOFORM

was of no concern with rudders remaining near neutral in forward level flight at all speeds above approximately 25 - 30 kt

CYCLIC TRIM AIDED FLIGHT 8

The near neutral longitudinal stability and flat power required curve from 40 kt IAS to 60 kt IAS required more pilot effort from a test standpoint. However, operationally flight at cruise speed could be made hands off for long periods of time within more restriction airspeed, attitude changes than present helicopters except those equipped with automatic stability or the RU-IA.

Noise level and vibration were satisfactory in cruise with and without doors open. Buffet and tail kicks were not observed by the pilot.

Transition to descent presented an unusual trim change. With reduction in power, the nose attitude would remain essentially the same. However, the airspeed would increase rapidly and required a nose high descent to obtain the trim speed for level flight again.

Operations from mountains or altitude will be hindered since limit is easily exceeded. Descents also require a large directional control trim change leaving very little left rudder remaining.

LANDINGS AND APPROACHES TO LANDINGS:

Tactically, the test aircraft is more restrictive during approach than the V. S. aircraft of similar mission. At high gross weights

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9
CONFIDENTIAL-SENSITIVE-NOFORN

the right rudder required during approach to hover is excessive and at many times full central was used.

Roll on landings were acceptable below 20 kt with nose wheel shimmy above that speed. Vertical touchdowns were satisfactory. Tail low hover prohibited quick stops in addition to the power/collective synchronization lag.

CONFIDENTIAL - JETS ITTV - TOF JEST

THE PROPERTY OF

I STABILITY

- 1. There is an improvement in the stability characteristics over comparable single rotor helicopters without ASE. Believed to be due, in part, to the:
- (a) extreme flexibility of the rotor blades giving the effect of a more outboard flapping hinge.
- (b) -3 arrangement giving a nirect kinematic linkage much that the pitch on an upward flapping plade is reduced resulting in a resistance of the rotor to change (i.e., gusts, etc.,).
- -- (c) linkage between borizontal stabilizer and collective pitch -----
 - 2. Static stability tests resulted in:
 - (a) Stable directional gradient at 33, 66, 83.5 kt IAS.
- Copperson (b) Positive dihedral effect at 33, 66, 83.5 kt IAS.
 - (c) Stable longitudinal gradient at 66 and 83 kt IAS; neutral to negative gradient at 35 kt IAS.
 - 3. Dynamic maneuvers determined the following:
 - (a) Slowly divergent phugoid about trim speeds of 49.5 kt and 63 kt IAS.
 - (1) Time for one cycle, approximately 20 sec.
 - (2) Pitch-roll coupling appears roll will diverge at a faster rate than pitch.
 - (b) Longitudinal step inputs.
 - (1) 1" aft input meets specification MIL-H-8501 in that "time history of normal acceleration becomes concave downward within 2 sec." about all speeds tested.

CONFIDENTIAL-SENSITIVE-NOFORM

DOWNGRADED AT 12 YEAR

NOT AUTOMATICALLY

DOD DIR 5200.10

Approved For Polesse 2000/05/16 COA PDP84

- (c) Longitudinal pulse inputs:
 - (1) Good short period damping.
 - (2) Induce long period phygoid.
- (d) Directional damping (establish sidealip and neutralize pedals) about 60 kt TAR in moderately gusty air.
 - (1) Dampers to half amplitude in approximately 3 sec.
 - (2) Time for cycle. approximately 4 sec.
- (3) undamped restaudle ossillations of approximately 5° total amplitude:
- (4) Limited tests indicate possible long period phugoid type of oscillations about which this short period "fish tailing" is oscillating (estimate approximately 25 sec for half cycle, and maximum initial half amplitude approximately 6° left sideslip regardless of direction of initial displacement). NOTE: 3 & 4 possibly due to turbulent air.
 - (e) Lateral pulse imputs.
 - (1) Slowly divergent oscillations as indicated by AF.

II CONTROL

- 1. Control positions and throws are comfortable.
- (a) Longitudinal and lateral force gradients are higher than desired.
 - (b) Directional control gradients are light in comparison.
 - (c) Total control throws (from handbook) are as follows:

Directional: 7.6 in

Longitudinal: 7.8 in

Lateral: 6.0 in

2

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9 CONFIDENTIAL SINGIFIC HOLDS

- 2. Control motion (Variation, with trim mirspeed).
 - (a) Flat longitudinal control motion.
 - (b) Lateral control motion is considerable.
- (1) Lateral control moves from 45% FF left at 40 kt IAS to 34% FFL at 70 kt IAS.
- (c) Rudder pedals in approx. mid position from 30 kt IAS to 90 kt IAS.
 - (d) Right rudder could become critical in a hover.
- 3. Trim rates and operation have desirable characteristics. Approximate rates are as follows:
 - (a) Longitudinal: 3.9#/Sec.
 - (b) Lateral: 3.34/Sec.
 - (c) Directional: 9.3%/Sec.
 - 4. Control power is adequate.
 - 5. Collective/throttle operation:
- (a) Synchronization is excellent. Throttle need not be adjusted for various cp settings after it is once set (max throttle).
- (b) Precise maneuvering with rapid collective displacements prohibited by lag of engine to power demand.
- release that must be held depressed with the left thumb.

III FLYING QUALITIES - general.

- 1. Level flight attitudes throughout speed range.
 - (a) Pitch attitude change of only 3% from 30 kt to 90 kt IAS.

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9 CONFIDENTIAL-SENSITIVE-NOFORN

- 2. Excessive handbook limitations on directional maneuvers in hover (crosswind, turns, etc.)
 - 3. Vibration acceptable, worse in transition to hover.
 - 4. Comfortable cockpit with ample room and comfortable seat.
 - 5. Trim indicators are desirable and good CG check.
- 6. Holds airspeed well (over 40 kt IAS) for a helo in operational use.
 - 7. Slight lag in response about all three axis.
 - 8. Inadequate field of view.
- 9. Fuel tank aft CG moves forward as fuel is burned (I inch CG travel for 185# of fuel at normal takeoff gross weight).
 - 10. Control effectiveness (longitudinal) weaker than desirable.

IV PERFORMANCE

- 1. Appears to have flat power required curve.
- 2. V max not limited by power available. With a roter system capable of higher stresses, V max would be considerably higher.
 - 3. Hover computer appears reasonably accurate.
 - 4. Weight empty: 11,311#.

Normal gross weight: 15.765#.

Overload gross weight: 16,647#.

Diameter of main rotor: 69.

Maximum power: 1700 BHP @ 2600 RPM.

(a) Ratio of payload to total weight is below comparable

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9 ONFIDENTIAL-SENSITIVE-NOFORK

- (b) Power loading: 9.28%/MP (Comparable to American).
- (c) Disc loading: 4.22#/ft2 (Less than most American).
- 5. Forward tilt of main rotor mast (5°) improves parasite drag and, therefore, allows for a reduction in power.

V MAIN ROTOR SYSTEM

- 1. Delta 3 hinge.
- 2. Flexibility of blades.
- 3. Mast tilt.
- 4. Friction lead-log dampers.
- 5. Hunting hinge outboard.
- 6. Flapping hinge close to center of hub.
- 7. Rotor hub has a built-in precision for each blade.
- 8. Blades (fabric covered) incorporate twist and taper.

VI In general, the following are considered advantages of the test helicopter under operational conditions:

- 1. Not fatiguing.
 - (a) CP/throttle synchronization during cruise flight.
- (b) Seat and cockpit.
 - 2. Reasonable platform for instrument flying.
- (a) Less instability than comparable helicopters without ASE.
 - (b) Level attitude 31/2°, 30 kt 90 kt IAS.
- (c) Static stability (directional, lateral & longitudinal above approximately 40 kt).

CONFIDENTIAL-SENSITIVE-NUTURE

- (d) Good short period damping.
- (e) Pedals neutral throughout speed range (30 kt Vmex).
- (f) Holdsairspeed well (for a helicopter) over 40 kt.
- 3. Radio altimeter. Good response and meedle stabilized over all types.
 - 4. Good stability in a hover.
 - 5. Trim system.
 - (a) Trim rates and operation.
 - (b) Indicators check on CC.
 - 6. Flat power required curve.
 - 7. Spark plugs good for life of engine.
 - 8. Signal flares controlled from cockpit. (Other usages for system).
 - 9. Grounding wire for sling loads:
 - 10. Accessible instrument panel.
 - 11. Ice prevention.
 - (a) MRB ice detection.
 - (b) MRB & TRB de-icing.
 - (c) Windshield anti-ice & de-ice systems.
 - 12. Armament capability.
 - 13. Fuel boost pump.
 - (a) Field refueling.
 - (b) Internal auxiliary fuel.
 - 14. Rear loading.
 - 15. Computer.
 - 16. Overall vibration level.

CONFIDENTIAL-SERVITIVE-NOFOLL

VII The following disadvantages were noted:

- 1. Pitch-roll coupling.
 - (a) Lateral control motion with change-trim airspeed.
- 2. Critical right rudder in hover.
 - (a) Sidewind and downwind hover.
- 3. Trim change in transition to and from a hover.
- 4. Limited maneuvering (throttle/CP synchronization).
- 5. Starter hang-up.
- 6. Collective fatiguing in hover (release button) at critical gross weights.
 - 7. Lengthy warm-up (70° 80°F OAT).
 - (a) 10 min oil warmup.
 - (b) 3 min engagement.
 - (c) 3 5 min launch.
 - 8. Handbooks poorly written.
 - 9. Fueling (location of fuel port).
 - 10. Big size.
 - 11. 60 4m clearance of tail rotor (approx.).
 - 12. Engine maintenance accessibility.
- 23. Tow bar arrangement.
- 14. Heavy transmission, head and in most construction.
- for radio altimeter)
 - 16. Van limited by structural considerations.
 - 17. Overall cockpit field of view.

CONFIDENTIAL-SENSITIVE-HOPOEN

Lonfidertial-Jeveltivi-Bufori

HELICOPTED PERFORMANCE SLIDE RULE

A computer was constructed on vellum identical to the subject slide rule with the necessary changes to "conventional" scales (meters to feet; Kg to lbs; etc.). The appropriate conversions were provided in the modifications. An enclosure is provided showing the four faces of the slide rule. A&C are attached, with B free to slide between. A movable hairline is provided as in a conventional slide rule. The reverse side provides E sliding between D&F.

The hover computer (A. B & C) provides a very good and easy method of computing maximum gross weight for hovering out of ground effects, and the maximum gross weight at which the helicopter can successfully be taken off, (or maximum gross weight for in ground affect hovering). The data used are the ambient conditions under which the helicopter will be operated. The computer is small (fits in the pocket of a flight suit) and appears to be fairly accurate.

It is believed that various restrictions of the aircraft are included on the table on the left side of A, B & C. To determine the maximum takeoff gross weight, the movable cross hair is placed at the intersection of the ambient pressure altitude and outside air temperature. The senter slide (B) is then moved so that the appropriate wind (top seale) is under the cross hair. It then is an easy matter to look over the proper specific humidity and read the maximum gross weight for

CONFIDENTIAL-SENSITIVE-NOFORM-

DOWNGRADED AT 12 YEAR

INTERVALS: NOT AUTOMATICALLY
DECLASSIFIED. DOD DIR 5200.10

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9

CONFIDENTIAL-SENSITIVE-NOFORN

takeoff. Because wind effect varies IGE & OGE, the bottom of scale B and scale C are used for maximum hovering OGE gross weight. The method of calculation is the same, however. By being able to simply calculate maximum weights with one motion, the A, B & C side of the slide rule demonstrates a very ingenious and well-designed innovation.

Test instrumentation and necessary ballast installations necessitated a high minimum weight restriction. This restriction and the high density attitude at the test size prohibited OGE hovering, so the OGE performance data could not be properly checked. At a gross weight of approximately 14,700%, hovering OGE was not possible at the test site. The computer, figured for the ambient conditions during the tests, provided the maximum gross weight for OGE hovering to be 14,100% to 14,200%. It was apparent during the test that the helicopter could malacest hover OGE.

Normal gross weight (approximately 15,800#) takeoffs were conducted on numerous occasions. When ambient conditions indicated on the slide rule a maximum gross weight takeoff, the opinion of the pilet verified the observation.

The reverse side (D, E & F) was not cheeked and therefore no comment
is made. Difficulties in translation and interpretation present
difficulties in understanding the intent. The proper scales and
factors are presented, however, for further study. It is believed

Approved For Release 2000/05/16: CIA-RDP81B00880R000100110002-9 CONFIDENTIAL-SENSITIVE-NOFORN

that the D. E & F side is utilized for determination of optimum range and endurance flying.

It is believed that a similar slide rule could be improved upon and beneficially utilized by operators of present American helicopters.

CONFIDERTIAL BENSITIVE-HOFORE

QUALITATIVE EVALUATION OF JAY PER-2 RADIO ALTIMETER

During normal tests of the H-36 aircrost, operation of the PBZ-2 altimeter indicated that the instrument responded correctly to terrain height variation in level flight, turns and longitudinal pitch changes. The instrument needle responded immediately to aircraft altitude changes and sould be read accurately to 1 meter (3.28 ft). The needle was well canpend.

with the altimeter installed in the n-3-, response and stability of the instrument remained the same. The calibration of the instrument had changed and some random fluctuations, similar to stray voltage inputs, were noticeable.

Tests involved flights over the dry lake bed, farm fields, rolling hills, buildings and mountainous terrain when enroute to Pt. Mugu. The instrument responded in the proper direction from 30 meters to 900 meters above the terrain. At Pt. Mugu, flights over water, beach, swamps, runways and roads were conducted from 5 meters to 30 meters at V from 5 kts to 85 kts. Flight paths were at intersection angles from water to shore at 90° - 45° and 15°. Sideward flight at 5 kts from the water to shore was made in addition to turns up to 35° bank angle with ASW approaches to hover and forward flight over water.

In all cases the instrument responded properly to all altitude changes, and was very steady. Variation in aircraft pitch attitude

CONFIDENTIAL-SENSITIVE-NOFORN

DOWNGRADED AT 12 YEAR

FERVALS; NOT AUTOMATICALLY

BECLASSIFIED, DOD DIR 5200.10

Approved For Release 2000/05/16 : CIA-RDP81B00880R000100110002-9-15-12

CUPIDENTIAL -SENSETIVE-HOFORN

up to 15° mose high and roll to 35° did not reveal any change in altitude indications over water or land. A few random oscillations, believed caused by some stray voltage incurred with reinstallation in the H-34, were noticed. When flying over a high voltage power line a large deflection of the needle - from 5 to 35 meters, occurred.

Breakdown of the needle with a rapid rise from 15 to 50 meters occurred over the lake bed in an extreme nose high flare of approximately 25° to 30°. This maneuver was extreme, however.

CONCLUSIONS:

- 1. The instrument is very steady with accurate response changes at the time the aircraft passes over the obstacle.
- 2. Altitude indication is held throughout all normal maneuvers over all types of terrain and water to shore.

RECOMMENDATIONS:

1. It is recommended that the entire installation and instructions be sent to the Naval Air Development Center, Johnsville, Pa. for evaluation.

NOTE: The stray voltage inputs observed with the altimeter installed in the H-34, that were not noticed in the H-36, may be one of the reasons why the H-36 has all the bonding wire installed.

2000/05/16 : CIA-RDP81B008 000100110002-9 UNITED STATES GOVERNMENT

25X1A

MEMO NO. 16-61

TO

DPD/DB

ATTN:

DATE:

14 July 1961

FROM:

EE/OPS/EX -

25X1A

SUBJECT:

Flight Report on the H-36 Helicopter

The attached is forwarded in accordance with your request and may be retained by you. Please note that it was received unofficially from AFSC. The final report is in process of review prior to publication, and we are promised a copy by the Air Force when it is published. If you are interested, we will make the final report available to you.

CONFIDENTIAL

Approved For Release 2000/05/16: CIA-RDP81